

MTI LADY READING HOSPITAL, PESHAWAR

SPECIFICATIONS FOR REPAIR & MAINTENANCE OF LIFTS

S.No	Description	Rate
1	Providing and installation of fully imported VVVF microprocessor controller with standard features such as micro push collective, selective system (MPCSS). Self diagnostic system, phase protection and all European standard safeties and option each system.	
2	Digital speed encoder	
3	Landing door fully automatic side opening in hairline stainless steel finish safety bridge and locking contacts door size: 1100 X 2100 mm (W xH)	
4	Providing and installation main motor with gear box complete set	
5	Landing board with digital display each	
6	Travelling cable each set	
7	Car Board for five to six floor with digital display	
8	Automatic side opening door drive in Hairline Stainless Steel finish with safety Bridge and locking contracts Door Size 1100X2100 mm (W x H)	
9	Electronic door detector (door safety)	
10	Door Shoes	
11	Push Buttons for Sigma OTIS Lift	
12	Display Card Sigma OTIS Each	
13	Guide Shoes Each	
14	Magnetic Contactor	
Total Cost (RS)		

Conditions for Lift Repair Contract:

- 1.0 The Replace parts must be returned to Equipment store MTI Lady Reading
- 2.0 The Acceptance of the Repair work will be subject to Inspection by inspection Committee / Electrical Engineer LRH.
- 3.0 Crain, Transportation and checking of defective lifts will provide by workshop free of cost.
- 4.0 If the repair work /parts is found below standard or does not confirm to our requirement will be Rejected.
- 5.0 Warranty /Guarantee of the repair and replaced parts will be 05 months.
- 6.0 Before opening the defective lift and taking defective parts for repair, the defective generator should be inspected in the presence of electromedical engineer of this hospital.